

## Safety Issue Type: Recalls

**May 10 2017** NHTSA Campaign Number: 17C001000

### Child Seat Webbing may Tear Under Load/FMVSS 213

A child that is not adequately restrained in a crash has an increased risk of an injury.

**NHTSA Campaign Number** 17C001000

**Manufacturer** Graco Children's Products Inc.

**Components** CHILD SEAT

**Potential Number of Units Affected** 25494

#### Summary

Graco Children's Products Inc. (Graco) is recalling certain Graco My Ride 65 convertible child restraints, models 1871689, 1908152, 1813074, 1872691, 1853478, 1877535, 1813015, and 1794334. In the event of a crash, the child seat webbing may not adequately restrain the child. As such, these car seats fail to conform to Federal Motor Vehicle Safety Standard (FMVSS) number 213, "Child Restraint Systems."

#### Remedy

Graco will notify owners, and dealers will provide consumers with a replacement harness, free of charge. The recall is expected to begin July 17, 2017. Owners may contact Graco customer service at 1-800-345-4109.

#### Notes

Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to [www.safercar.gov](http://www.safercar.gov).

## Associated Products (1)

### Child Seat

GRACO	MY RIDE 65	9999
-------	------------	------

## Associated Documents (3)

Recall 573 Report

**RCLRPT-17C001-6403.PDF** 219.088KB

<https://static.nhtsa.gov/odi/rcl/2017/RCLRPT-17C001-6403.PDF>

Recall 573 Report - Amendment 1

**RCLRPT-17C001-2923.PDF** 219.19KB

<https://static.nhtsa.gov/odi/rcl/2017/RCLRPT-17C001-2923.PDF>

Recall 573 Report

**RCLRPT-17C001-5885.PDF** 219.088KB

<https://static.nhtsa.gov/odi/rcl/2017/RCLRPT-17C001-5885.PDF>